


Environment Requirement

- Operating Temperature and Relative Humidity
0°C to +40°C, 20%RH to 80%RH @ altitude should be below 10000 feet.
- Storage Temperature and Relative Humidity
-20°C to +60°C, 10%RH to 90%RH (non-condensing) @ altitude should be below 30000 feet.

Installation Method



Note:

- (1) Screw fixture design enable you to secure the TX module to a range of work top thickness (17mm~40mm).
- (2) Fits the TX module into the hole in work surface from top.
- (3) Fits the screw fixture to a range of desk thickness and fix it with the screws.

Others

- Size : $\Phi 84 * 44$ mm
- Weight : 138 ± 3 g
- Please use the correct AC Adapter, to ensure the normal function.